

**EXHIBIT 17**

## TECHNICAL ASSISTANCE CENTER

\*\*\*\* GM RESTRICTED \*\*\*\*

Case No:	08224557	VIN:	Privacy
Date Opened:	20050602	Model Year:	2005
Date Closed:	12/31/2010	Model Series:	AG
Dealer Code:	?121937	Mileage:	008827
Dealer Name:	Saturn Of Puyallup, Puyallup	Dealer State:	WA
Dealer Phone:	2538406300	Division:	Saturn - GM

---

SYMPTOM ABSTRACT— INTERMITTENT STALL

RESOLUTION ABSTRACT-

UCC CODE 1-----

UCC-1 DESCRIPTION— Engine

UCC CODE 2-----

UCC-2 DESCRIPTION—

UCC CODE 3-----

UCC-3 DESCRIPTION—

06/02/2005 12:54:11 SBD Template - WENDELL

STRATEGY BASED DIAGNOSTICS

\_1\_ Number of times in for the same condition

\_1\_ Number of days vehicle in dealership for same condition

\_n\_ Y / N Is the vehicle modified/non-production accessories (List below)

\_n\_ SI Document ID Number supplied by Dealer \_\_\_\_\_

Caller's name (First, Last, and Position)

Privacy Tech

Customer concern -

Stall

Dealer comments/diagnosis -(DTC'S, Parts, Repairs, Duplicated, SI

Search, Compare to like Vehicle?)

Tech ahs duplicated stall and it is intermittent.

Tech alleges there are not DTC

Tech is looking for possibilities at this point.

## ***TECHNICAL ASSISTANCE CENTER***

**\*\*\*\* GM RESTRICTED \*\*\*\***

***Case No:*** 08224557

***VIN:***

**Privacy**

***Date Opened:*** 20050602

***Model Year:*** 2005

***Date Closed:*** 12/31/2010

***Model Series:*** AG

***Dealer Code:*** ?121937

***Mileage:*** 008827

***Dealer Name:*** Saturn Of Puyallup, Puyallup

***Dealer State:*** WA

***Dealer Phone:*** 2538406300

***Division:*** Saturn - GM

---

***TAC recommendation -***

*Advised tech to evaluate the ignition switch , wiring and grounds for possible concerns as per like cases.*

*No other recommendations given tech is to report back if further assistance is needed.*

**06/02/2005 12:54:11 History - WENDELL**